



*Diesel Fuel Line
(Susceptible to Damage)
(Not Protected)*

*Waterville Valley Resort LLC
1 Ski Area Road
Waterville Valley, NH 03215
03/30/12 USEPA Inspection*

*Mobile Refueler/Snow Cat
300- Gallon Oil Tank
&
Secondary Containment Area*

*Debris in Containment Area
(Clean Regularly)*

*Drain
(Not Capped)
(Install Drain Plug)*

*Waterville Valley Resort LLC
1 Ski Area Road
Waterville Valley, NH 03215
03/30/12 USEPA Inspection*






*Mobile Refueler/Snow Cat
300-Gallon Oil Tank Onboard*

*Water w/Oil Leak from Oil Tank's Secondary Containment Area
(Inspect and Document Liquid for Oil Sheen Prior to Discharge)*


*Waterville Valley Resort LLC
1 Ski Area Road
Waterville Valley, NH 03215
03/30/12 USEPA Inspection*



*Mobile Refueler /Snow Cat
Oil Tank's Supply Hose to Nozzle
(Union Not Proper)
(Hose Cracking & Leaking)
(Needs Service/Replace)*

*Waterville Valley Resort LLC
1 Ski Area Road
Waterville Valley, NH 03215
03/30/12 USEPA Inspection*

*Food Oil Waste Containers
(No Secondary Containment)
(Oil Spillage on Ground)
(Clean)*



*Waterville Valley Resort LLC
1 Ski Area Road
Waterville Valley, NH 03215
03/30/12 USEPA Inspection*